


Tasmania Shipping Info Sheet

- Tie down points need to be provided for outboard use on all four corners of vehicle and labelled prominently. Shipping company hooks for “tie-down” typically need approx. 60mm x 40mm “engage opening” (hole size).



- Ensure any vehicle with air bag suspension has “good condition” air bags.
- Label any air bag controls with clear operating instructions (raise, lower, etc)
- Label and have access to any “landing leg”, handles, operating instructions, etc.



- Ensure all driving vehicles have “satisfactory starting” for load and unload (good battery, etc).
- Provision for shipping labels needs to be visible @ R/H bottom corner of windscreen inside cabin and R/H corner of all trailers.
- Delivery driver (and any additional people going onto wharf) need to wear fluoro vest/clothing at all times in wharf area.
- Confirm adequate detail of correct “first stop point” @ check-in/arrival and parking/drop-ff detail (varied across each shipping company).
- Confirm with shipping company on “arrival time @ wharf” for loading and approx. pick-up time @ voyage end.
- Delivery driver needs to have registration numbers and gross weights of all vehicles – (tow vehicles, trucks, trailers) when first speaking to shipping company staff @ check-in/arrival (on-hand/easy access)
- All keys for vehicle movement (ignition, etc) and relative/necessary compartments must be left with vehicle.

Spirit of Tasmania - Shipping Info Sheet

When travelling on the Spirit of Tasmania

Before you arrive at either Geelong or Devonport check that you have a fully paid booking for the freight and driver (they are separate), and if travelling on a night sail that you have a room booked.

Check that you are not carrying any Dangerous goods as detailed on Spirit of Tasmania website <https://www.spiritoftasmania.com.au/terms-and-conditions/carriage-of-dangerous-goods> (air bottles, fuel etc).

Freight units must be received 3 hours prior to departure on a night sailing, and 2 hours prior to departure on a morning sailing

Freight units are subject to security screening prior to acceptance into the freight yard Upon arrival, you will be required to provide the following information:

- Booking Reference number
- Unit Details (registration, nett weight & gross weight)
- Commodities

When driving in the freight Yard turn hazard lights on.

Mandatory Biosecurity Check Point at 110 Wright Street, East Devonport, Tasmania. Located on right hand side of Wright St and Entry is just after (approx. 100m) Sea Road office / wharf complex.

